



National Transportation Safety Board

Human Performance Issues



Maintenance Errors

- Improper securing of the fore/aft servo
- Improper tension of the hydraulic belt
- Incomplete maintenance inspection

Overview

- Maintenance personnel fatigue
- Human factors training for maintenance personnel
- Work cards with delineated steps

Maintenance Personnel Fatigue

- The mechanic
 - Recent sleep and wake activity
 - Earlier bedtime than normal but had difficulty falling asleep
 - Shift change
 - 6 hours earlier than normally scheduled shift
 - Inadequate sleep
 - 5 hours of sleep the night before

Maintenance Personnel Fatigue

- The inspector
 - Recent sleep and wake activity
 - 7 hours of sleep the night before
 - Shift change
 - Over 6 hours earlier than normally scheduled shift
 - Long duty day
 - Over 14 hours

Maintenance Personnel Fatigue

Personnel	Normal Shift	Actual Shift on December 6	Duty Length	Time Awake
Mechanic	Noon to 11:00 pm	5:50 am to 6:46 pm	12:56	13:46
Inspector	Noon to 11:00 pm	5:31 am to 6:55 pm	13:24	14:55

Maintenance Personnel Fatigue

- Effects of fatigue
 - Difficulty sustaining attention
 - Memory errors
 - Lapses in performance

Duty-Time Regulations

- ValuJet Airlines accident (1996)
- Establishing duty-time limitations based on the following:
 - Start time
 - Workload
 - Shift changes
 - Circadian rhythms
 - Adequate rest time

Human Factors Training

- Causes of fatigue, its effects, and countermeasures
- Fatigue education as part of a training curriculum
- No human factors training requirement in United States

Work Cards With Delineated Steps

- Paperwork for 100-hour inspection
- Inspector signoff for overall fore/aft servo installation
- No specific signoffs for critical steps within task

100-Hour Inspection Paperwork

MAKE		Eurocopter		DISCREPANCY LIST		DATE		12/08/11	
MODEL		AS350B2		SUNDANCE HELICOPTERS		AF TT		25216.5	
S/N		2300		5598 Haven Street		ENG TT		7400.0	
REG.		N37SH		Las Vegas, Nevada 89119		PAGE		4 of 10	
DISCREPANCY				CORRECTIVE ACTION					
No. 15				RMVD M/R F/A SERVO SN RX 187 TSO: 1959.5 TSN: 14202.3. INST'D O/H UNIT SAME PN SN BX 284 TSO: 0.0 TSN: 21150.9. ALSO REPLACED ALL ORINGS PN 81810-110-24B7 PO 9048. REF AS 350 M/M CH 67					
M/R F/A SERVO PN AC67246 SN RX 187 DUE O/H				signoff					
Name		Date 12-6-11		Signature		Cert. No.		Date 12-6-11	
No. 16				RMVD T/R SERVO SN FE 212 TSO: 1959.5 TSN: 12328.4. INST'D O/H UNIT SAME PN SN DK287 TSO: 0.0 TSN: UNK. ALSO REPLACED ALL ORINGS PN 81810-110-24B7 PO 9048. REF AS 350 M/M CH 67					
T/R SERVO PN AC67032 SN FE 212 DUE O/H									
Name		Date 12-6-11		Signature		Cert. No.		Date 12-6-11	
No. 17				Removed Arriel 1D1 Engine S/N 9399 Engine T.T. 11226.1 Total Ng 13996.03 . Total Np 15499 . Reference AS350B2 AMM Chapter 71-11-00 Para 4-1. Engine tagged appropriately.					
Remove Arriel 1D1 Engine S/N 9399									
Rental									
Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>									
Name		Date 12-6-11		Signature		Cert. No.		Date 12-6-11	
No. 18				Installed serviceable Arriel 1D1 Engine S/N 9043 Reference AS350B2 AMM Chapter 71-11-00 Para 4-2.					
Install Arriel 1D1 Engine S/N 9043 Engine T.T. 2400.0 Total Ng 2667.2 Total Np 7845.3									
Rental									
Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>									
Name		Date 12-6-11		Signature		Cert. No.		Date 12-6-11	
No. 19				Cleaned Air Duct ref. Arriel 1D1 MM 71-03-110-801-A01.					
Clean the Air Duct.									
Name		Date 12-6-11		Signature		Cert. No.		Date 12-6-11	

SOM-002 Revision: Original

Work Cards With Delineated Steps

Sample work card

DESCRIPTION		MECH	INSP
D.	Check trunnion bearings and drag brace bearing for proper installation and freedom of movement.		
3.	INSTALL NOSE LANDING GEAR - REFERENCE AMM		
→ A.	Support gear and jack with axle jack to insert trunnion pins in respective spherical bearings (13) on each side of the nose gear wheel well.		
→ B.	Jack gear to proper height and tap trunnion pin into place in each trunnion and trunnion support spherical bearing (13) then remove axle jack. NOTE: NOSE GEAR MUST BE LIFTED INTO POSITION WITH GEAR TRUNNION AXIS PARALLEL TO TRUNNION BEARING AXIS.		
→ C.	Ascertain that the trunnion pin lockpin holes are in alignment with mating holes in trunnion pin lockpins.		



National Transportation Safety Board